T T 7		\sim	1 '	TT	5805	•
W O	ru		nan		>XII	,
7 T U	71 IN	\mathbf{v}	ucı	117	- 2002	_

April 22, 2010 11:55:56 AM



Page 1

D4039-041 Item ID: Accept Setup Start **Revision ID:** Stop Item Name: Fwd Bracket Assembly **Start Date:** 22/04/2010 Start Qty: 2.00 **Cust Item ID: Required Date: 29/04/2010** Req'd Qty: 2.00 **Customer:** Reference: Run Start Date: 10-4-27 Tooling: Process Plan: Approvals: Date: Stop Date:___ SPC (Y/N): Date: Sequence ID/ Operation Set Up/ Plan Draw Draw Accept Reject Reject Insp. Work Center ID Description **Run Hours** Number Rev. Code Qty **Qty** Number Stamp **Draw Nbr Revision Nbr** D4039 Α 100 0.00 Small Fab 0.00 of colo4/29 Memo Small Fab 1- Assemble lanyard to bracket as per dwg QC5- Inspect part completeness to step on W/O Memo Quality Control

120

Packaging

Packaging

Memo

Identify as per dwg & Stock Location:

0.00

0.00

10-4-29

Dart Aerospace Ltd

W/O:			V	VORK ORDER CHANG	ES				
DATE	STEP	PROC	EDURE CH	IANGE	Ву	Dat	te Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									•
									į
Part No	:	PAR #:	_ Fault Ca	tegory:	_ NCR: Ye	s No	DQA:	_ Date: _	
	R	esolution:	_ Disposit	ion:	_ QA: N/C	Closed	:	Date: _	
NCR:		W	WORK ORDER NON						
DATE	STEP	Description of NC	12411	Corrective Action Section		V	erification	Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng	Sign Dat		Section C	Chief Eng	QC Inspector
							į		
							į		
									; ;
		:							
,									
1		1		1	1	1 1			1

Work Order ID 58052

April 22, 2010 11:55:56 AM



Page 2

Item ID:

D4039-041

Accept

Setup Start

Stop



Revision ID:

Item Name:

Fwd Bracket Assembly

Start Date:

Start Qty: 2.00 22/04/2010

Required Date: 29/04/2010

Rea'd Otv: 2.00



Cust Item ID:

Customer:

Reference:

Approvals:

QC:

Process Plan:

Operation

Description

Date:

Tooling:

SPC (Y/N):

Set Up/

Date:

Date:

Start

Run

Stop

Sequence ID/

Work Center ID

130

Quality Control

Memo

OC21- Final Inspection - Work Order Release

0.00

0.00

Run Hours

Draw Number

Draw Rev.

Plan Accept Code Oty

Reject Qty

Reject Insp. Number

Stamp

OC

Date: _____

Dart Aerospace Ltd

W/O:			V	VORK ORDER CHANG	ES						
DATE	STEP	PRO	CEDURE CI	HANGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
		,									
		1									
\ <u>\</u>											
Part No	•	PAR #:	Fault Ca	itegory:	NCR: Yes N	lo DQA:	Date: _				
	Re	esolution:	Disposit	tion:	_ QA: N/C Clo	sed:	Date: _				
NCR:			WORK ORDER NON-CONFORMANCE (NCR)								
DATE	STEP	Description of NC		Corrective Action Section		Verification	Approval	Approval			
	J.L.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector			
								}			
		•									
		I									
						;					
								-			

Picklist Print

April 22, 2010 11:56:01 AM

Work Order ID: 58052

D4039-041

Parent Item Name: Fwd Bracket Assembly

Parent Item:

Start Date: 22/04/2010

Required Date: 29/04/2010

Comments:	IPP RevA: new iss	ue DD 09.12.15	verifie	d by:EC				9	Start Qty: 2.00)	Required Qty: 2.	00
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D4039-1 Fwd Bracket		Manufactured	No			100	Each B579	0.0000	2.0000	/ S	10/04/29	
D2690-6 Lanyard Assembly		Manufactured	No			100	Each	7.0000	2.0000			
				Warehoo Loca Main Wa ST02	rehouse	Loc	<u>Qty</u> 7	Loc Code	_		1	2
BLRS-010 Pip Pin		Purchased	No		50665	100	7 Each	42.0000	2.0000		<u> इ</u> ह्ये की व्य	29 (<u>)</u>
				Warehoo Loca Main Wa ST28	rehouse 33 112689	Loc	<u>Oty</u> 42 22	Loc Code	_	1	- - So 10/04/) 29 (j)
MS27039-1-11	1 1811 1/1888 (1811 1/1888) 1/1888 (1811 1	Purchased	No		113779	100	20 Each	83.0000	2.0000			
				<u>Warehoo</u> <u>Loca</u> Main Wa	<u>ition</u>	Loc	<u>Oty</u>	Loc Code				_
				ST29	9662		83 83		, –		- Sis lolo	1/291)

Dart	Aerospace	Ltd

W/O:			W	ORK ORDER CHANG	ES				
DATE	STEP	PRO	CEDURE CH	IANGE	Ву	Date (Approval Chief Eng / Prod Mgr	Approval QC Inspector	
Part No	•	PAR #:	Fault Ca	tegory:	NCR: Yes	No DQA:	Date: _		
	R	esolution:	Disposit	ion:	_ QA: N/C Cld	sed:	Date: _		
NCR:	* .	V	ORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC	Description of NC Corrective Action Se				ion Approval		
	0.2.	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section		QC Inspector	
			,						
						į			
V									
	1				1	1	1	1	

Picklist Print

April 22, 2010 11:56:01 AM

Page 2

Work Order ID: 58052

Parent Item:

D4039-041

Parent Item Name:

Fwd Bracket Assembly

Comments:

IPP RevA: new issue DD 09.12.15 verified by:EC



Start Date: 22/04/2010

Required Date: 29/04/2010

Start Qty: 2.00

Required Qty: 2.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Primary Item Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
MS21042L3		Purchased	No		100	Each	1,087.000	2.0000			
		9									

Nut

<u>Warehouse</u>	<u>L</u>	oc Oty	Loc Code	
Location				
Main Warehouse				
ST300		1087		
11353	7	103		
11364	4	984		
No	100	Each	1,630.000	6.0000



Washer

Warehouse Loc Qty Loc Code Location Main Warehouse ST298 1630

113288 2 114292 1628

Ss 10/04/29


3 Soloy/28 ()

W/O:	Ì		WO	RK ORDER CH	ANGES						
DATE	STEP	PR	OCEDURE CHAI			Ву		Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto
			!								
Part No		PAR #:									
	Reso	lution:	Disposition	n:	QA	: N/C (los	ed:		Date:	
NCR:			WORK ORDE	D NON CONEC	BILANIA					:	
	•		WOIIK ONDE	ER NON-CONFO	RMANCE	E (NC	R)			1	
DATE	CTED			Corrective Action	Section B	`		Verific	ation	Approval	Approva
DATE	STEP	Description of NC Section A			Section B	Sign Date	&	Verific Section		Approval Chief Eng	Approval
DATE	STEP	Description of NC	Initial	Corrective Action Action Descrip	Section B	Sign	&				
DATE	STEP	Description of NC	Initial	Corrective Action Action Descrip	Section B	Sign	&				
DATE	STEP	Description of NC	Initial	Corrective Action Action Descrip	Section B	Sign	&				
DATE	STEP	Description of NC	Initial	Corrective Action Action Descrip	Section B	Sign	&				
DATE	STEP	Description of NC	Initial	Corrective Action Action Descrip	Section B	Sign	&	Section			
DATE	STEP	Description of NC	Initial	Corrective Action Action Descrip	Section B	Sign	&	Section			

QTY. -043 ITEM NO. PART NUMBER DESCRIPTION 1 D4039-041 **FWD BRACKET ASSEMBLY** 2 Х D4039-043 AFT BRACKET ASSEMBLY D4039-1 FWD BRACKET 4 D4039-3 AFT BRACKET 5 D2690-6 LANYARD BLRS-010 PIP PIN 7 1 MS27039-1-11 SCREW 8 1 MS21042L3 NUT NAS1149D0363J WASHER

SHOP COPY RETURN 10 **ENGINEERING** UNCONTROLLED COM SUBJECT TO AMENDMAN WITHOUT NOTICE:

WORK ORDER NO 58052



D4039-041 FWD BRACKET ASSEMBLY


BS10-4-22

D4039-043 AFT BRACKET ASSEMBLY

				•	'V"
Α	NEW IS:	SUE		as	09.12.14
REV.			DESCRIPTION	BY	DATE
DESIG	N	45	DART AER	OSPACE I	ĬD
DRAW	N	4		ONTARIO, CANAI	
CHECK	(ED	B	DRAWING NO.		REV. A
MFG. A	PPR.	21	□ D403 9		SHEET 1 OF 3
APPRO	VED	149	TITLE		SCALE
DE API	PR.	-#-	BRACKET		NTS
DATE	09.1	2.14	THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL A NOT TO BE USED FOR ANY PURPOSE OR COPIED	BY DART AEROSPACE NO IS SUPPLIED ON THE EXPRESS OR COMMUNICATED TO ANY OTH FROM DART AEROSPACE LTD	CONDITION THAT IT IS


NOTES:
1) MATERIAL: N/A
2) FINISH: N/A
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: N/A
6) IDENTIFICATION: IDENTIFY WITH DART P/N "D4039-041/-043" AND B/N USING FINE POINT PERMANENT INK MARKER
7) WEIGHT: N/A

W/O:			W	ORK ORDER CHANGES		ļ				
DATE	STEP	PR	OCEDURE CHA		Ву		Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspect
Part No):	PAR #:	Fault Cate	gory:	NCR: Ye	es N	o DQA	•	Date:	<u> </u>
	_					1				
	Reso	lution:	Dispositio	n: (QA: N/C	Clos	sed:			
NCR:	Reso	lution:	Dispositio		QA: N/C	Clos	sed:			
<u>.</u>		elution:	Dispositio WORK ORD	n: (ER NON-CONFORMAN Corrective Action Section E	QA: N/C CE (NO	Clos	sed:		Date:	
NCR:	Reso	lution:	Dispositio	n:(ER NON-CONFORMAN	QA: N/C CE (NO B	Clos	sed:	ation		
<u>.</u>		Description of NC	Dispositio WORK ORD	n: (ER NON-CONFORMAN Corrective Action Section E Action Description	QA: N/C CE (NO B	Clos CR)	sed:	ation	Date:	Approva
<u>.</u>		Description of NC	Dispositio WORK ORD	n: (ER NON-CONFORMAN Corrective Action Section E Action Description	QA: N/C CE (NO B	Clos CR)	sed:	ation	Date:	Approva
<u>.</u>		Description of NC	Dispositio WORK ORD	n: (ER NON-CONFORMAN Corrective Action Section E Action Description	QA: N/C CE (NO B	Clos CR)	sed:	ation	Date:	Approva



Dart Aerospace I	Ltd
------------------	-----

W/O:			W	ORK ORDER CHANG	SES			<i>a</i>		
DATE STEP		PRO	CEDURE CHA	NGE	Ву		Date Qty Approval Chief Eng / Prod Mgr		Approval Chief Eng / Prod Mgr	Approval QC Inspector
7										
Part No	:	PAR #:	Fault Cate	gory:	_ NCR: Y	es N	o DQA:		_ Date: _	
		solution:			1					
NCR:		; V	VORK ORD	ER NON-CONFORMA	ANCE (N	CR)				
DATE	STEP	Description of NC Section A	Corrective Action Section B				Verification		Approval	Approval
	JILI		Initial Chief Eng	Action Description Chief Eng		ın & ate	Section C	Chief Eng	QC Inspector	
										:
										i
	7									
 -										
									·	



Dart	Aerospace	Ltd
WIO.		

W/O:			WORK ORDER	CHANGES				
DATE	STEP	PF	OCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
~								
Part No	:	PAR #:	Fault Category:	NCR: Yes	No DQ	A:	Date:	
	Resolutio	n:	Disposition:	QA: N/C C	losed:		Date: _	

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
DATE	STEP	Description of NC Section A	Corrective Action Section B			Varidia adi an					
			Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector			
÷											
		r									
		,									
		•									
		· · · · · · · · · · · · · · · · · · ·									
•											